

Tech Help

Applications: 2002-2003 Suzuki Aerio w/MT
 2004 Suzuki Aerio w/MT Vin Up To JS2RA61S~45207965
 2004 Suzuki Aerio w/MT Vin Up To JS2RB61S~45200505
 2004 Suzuki Aerio w/MT Vin Up To JS2RC61H~45255378
 2004 Suzuki Aerio w/MT Vin Up To JS2RD61H~45252566

("~" indicates the check digit which will vary)

GSP Part Numbers: NCV68502

The driver side CV axle may pop out from the transmission during final drive. If this occurs it is due to the snap ring releasing from the differential side gear. The gears and snap ring must be replaced with the updated parts below:

Part Numbers	Description	QTY	Notes
27341-70C01	Differential Side Gear	2	Replace both side gears.
44111-65D00	Snap Ring	1	Replace left side only.
09205-05007	Spring Pin	1	One time use must be replaced.
44117-59J10	Joint Assy. Diff. Side LH 2004MY	1	Replace only if splines are damaged.
44117-54GK0	Joint Assy. Diff Side LH 2002, 2003MY	1	Replace only if splines are damaged.